

## MEDIA INFORMATION / PUBLIC INFORMATION WORKSHEET

Please email to PIO Larry Gallegos at <u>lagallegos@bernco.gov</u> (505) 228-6668

1.	Date/Incident number	11/08/2015 2015-016195
2.	Incident Address	4000 Blake Road SW Space #45 Albuquerque NM 87121
3.	Area of County	South Valley
4.	Mutual Aid request/given	Automatic aid area, closest unit response
5.	Reported by:	Property owner
6.	Fire Condition/Alarms	Moderate smoke showing from the roof/eave area of single wide trailer
	(working fire, 2 <sup>nd</sup> alarm)	
7.	Size & Type of Structure/Incident	Structure was a single wide trailer with enclosed attached garage
	(apt/residential home/ bldg)	
8.	Number of Personnel	E-33, E-34, Tr-38, R-32, R-33, R-34, Bat-8, Bat-6, FMO-33, AFD
	Responded (Units and FFs)	Arson-1
		Total personnel on scene:19
	Time Dispatched/1 <sup>st</sup> Unit Arrival time	00:03 dispatched, Arrival at 00:10
10.	Brief description of what 1 <sup>st</sup> unit on the scene saw.	Upon arrival found single wide mobile home with moderate smoke showing from perimeter of roof.
11.	Total time to bring fire under control	50 minutes
	Anyone inside at the time of the fire. If yes, how many	Two people were sleeping when fire occurred
13.	How was family alerted? (smoke detector, neighbors)	One person woke up to the smell smoke in the house and alerted the othe occupant. No working smoke detectors were found in the home.
14.	Injuries? If yes, include age, gender, transport info & injuries sustained.	No injuries reported
15.	Fire Origin? Was it contained to origin?	The fire started by the front door in the wall. The fire then extended into the built up double roof space. The roof was a flat roof with a secondary wood truss pitched roof over existing.
16.	Spread through %	60% of roof space was affected.
17.	Smoke Damage (light or heavy smoke damage throughout)	Light smoke damage to the interior of the home.
18.	Cause (determinded/undetermined>accident,natural,incendiary)	The cause was from improper electrical wire installation. The circuit was overloaded and created a short circuit. The short circuit created a fire in the wall at the front door. The cause is deemed accidental.
19.	Estimated Damages (structural, contents/vehicle)	15,000 in damage to structure
20.	Assisting Agencies like Red Cross, # of displaced?	AFD Arson investigator was used to determine cause and origin.
21.	Contributing factors such as wind or location	No contributing factors
	Additional information (rescues, FF injuries and so on)	
23.	On Scene POC	Commander Rose
	Community Risk Reduction Message	Make sure there are functioning smoke detectors. Always use licensed electricians for electrical remodeling.
25	Additional Information	